


# CES Environmental Services, Inc.

Dec 11, 2014





Katy Fwy

Harris

East Fwy

Houston

N Wayside Dr

Richmond Ave

Southwest Fwy

West University Place

Main St

South Fwy

S Wayside Dr

E Loop Fwy

225


4904 Griggs Rd, Houston, TX 77021, USA

© 2014 Google

Google earth

29°43'24.59" N 95°20'58.72" W elev. 55 ft eye alt 9.97 mi






4904 Griggs Rd, Houston, TX 77021, USA



10/2014  
1944 2014




Google earth

1944

Imagery Date: 4/8/2014 29°41'54.31" N 95°20'41.91" W elev 40 ft eye alt 1598 ft



























# Vacuum Boxes (12VB and 1 RO) - Removed





# Tank Trailers (2)





# Frac Tanks (11)





# ASTs (23)






# Totes/Drums





# Lab Pack (completed by Estate)





## Vats (4)





# Asphalt/Concrete Areas





# Wastewater Treatment Tanks (19)





# Activities Completed to Date (12/11/14)

- Container Sampling/Analysis
  - All of the large containers for the most part have been sampled/analyzed (additional sampling will be necessary)
- Disposal
  - 12 of 12 Vacuum Boxes transferred/disposed
  - 1 of 1 Roll-off Box transferred/disposed
  - 2 of 11 Frac Tanks have been drained/disposed
  - 4 of 23 ASTs have been drained or partially drained/disposed
- Contaminated Storm Water Management
  - Storm Water collected on property is discharged to sanitary sewer or otherwise drains off-site
- Odors
  - Odors will not dissipate until all wastes have been disposed and spill areas cleaned. Hopefully, you will begin to notice some reduced odors as material is disposed.